



Norman H. Bangert
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

July 9, 1992

TO: Minerals File

FROM: Tony Gallegos, Reclamation Engineer *aa*

RE: Site Inspection, Lamb, Sessions & Young, Stone Quarry Mine, S/011/001, Summit County, Utah

Date of Inspection: July 8, 1992
Time of Inspection: 1515 - 1545
Conditions: Partly cloudy, warm
Participants: Tony Gallegos, DOGM

The purpose of this inspection was to evaluate the status of this mining operation. No Division inspection had been performed since the notice was received in September 1990.

The legal description for the site is located adjacent to Interstate 84. The general location described in the notice was examined on foot, since the old road was blocked with boulders. The mine site is believed to be in the bend of the old highway and on the south bank of the Weber River. An old quarry site exists in this area, but showed no signs of recent activity. No other signs of a mining operation were found in this area on the north side of the Interstate. A photograph of the quarry area was taken. The operator should be contacted to confirm the location and status of the mine site.

jb
cc: Lamb, Sessions & Young
S011001



7-8-92

LAMB, SESSONS & YOUNG SITE?

5/01/001